



	12.	Digital Multimeter	x2		
E V V	13.	Clip On Meter Or Clamp On Tester	x3		S S S
	14.	Hi-Potential test Set	x1		* * *
	15.	Megger(Analogue)	x2		
	16.	Earth Tester	x2		3
	17.	Transformer Oil Testing Kit (Optional)	x1		
	18.	Discharge Rod	x1		
	19.	Ladder	x1		
	20.	Safety Helmet, Rubber Gloves, Safety Sign Board, Safety Belt Or Full Body Harness, Safety Boot, Tagging	x2		
	21.	Rubber Mat	x1		93
					N·S·D·C National Skill Development Corporation Transforming the skill landscape



- 1. **PSS N 0105** : (Repair and maintenance of power distribution lines and components)
- 2. PSS N 0107 : (Operation and maintenance of 11/0.433 KV Distribution Substation)
- 3. PSS/ N 2001 : (Use basic health and safety practices for power related work)
- 4. PSS/ N 1336 : (Work effectively with others)

- 1. Each Performance Criteria (PC) will be assigned marks proportional to its importance in NOS. PSSC will also lays down proportion of marks for Theory and Skills Practical for each PC.
- 2. The assessment for the theory part will be based on knowledge bank of questions created by the PSSC
- 3. Assessment agencies will create unique question papers for theory part for each candidate at each examination/training center
- 4. Assessment agencies will create unique evaluations for skill practical at each examination/training center
- 5. To pass the Qualification Pack, every trainee should score a minimum of 70% marks in every NOS
- 6. In case of successfully passing only certain number of NOS's, the trainee is eligible to take subsequent assessment on the balance NOS's to pass the Qualification Pack

evelopment

oration

Transforming the skill landscape

